

Appendices

Appendix A: Photographic Log

Date/Name	Photo
<p>Photo 1: 10/1/2014 Salina Junction looking southeast towards Fourmile Canyon Drive.</p>	 A photograph showing a dirt road that curves to the right. The road is light-colored and appears to be made of gravel or compacted earth. On the left side of the road, there is a rocky embankment with some sparse vegetation. The background is filled with dense trees, some of which have yellow and orange leaves, suggesting an autumn setting. The sky is bright and clear.
<p>Photo 2: 10/1/2014 Fourmile Canyon Drive looking southwest.</p>	 A photograph of a dirt road stretching into the distance. The road is flanked by tall, green evergreen trees. On the right side of the road, there is a large, red metal barn with a dark door. A dark-colored car is parked near the barn. A utility pole with power lines is visible in the middle ground. The sky is blue with some light clouds.

Date/Name	Photo
<p>Photo 3: 10/1/2014 Demolished structures location, south of intersection along Fourmile Canyon Drive, looking southwest.</p>	
<p>Photo 4: 10/1/2014 Demolished structures location, south of intersection along Fourmile Canyon Drive, looking southeast.</p>	

Date/Name	Photo
<p>Photo 5: 10/1/2014 Fourmile Creek, looking southwest.</p>	
<p>Photo 6: 10/2/2014 Fourmile Creek, looking southeast.</p>	

Date/Name	Photo
<p>Photo 7: 10/1/2014 Inactive bird nest in elm tree west of intersection, along Fourmile Canyon Drive.</p>	
<p>Photo 8: 10/1/2014 North side of intersection looking towards 17 Gold Run Road.</p>	

Date/Name	Photo
<p>Photo 9: 10/1/2014 42-inch culvert for Gold Run underneath intersection, looking south.</p>	
<p>Photo 10: 10/1/2014 Gold Run east side of Gold Run Road, looking north.</p>	

Date/Name	Photo
<p>Photo 11: 10/1/2014 Gold Run Road, looking south.</p>	 A dirt road on Gold Run Road looking south. The road is wide and unpaved, with visible tire tracks. On the right side, there is a house with a grey roof and a concrete wall. The background shows a dense forest of evergreen trees under a cloudy sky.
<p>Photo 12: 10/1/2014 Gold Run Road, looking north.</p>	 A dirt road on Gold Run Road looking north. The road is wide and unpaved. On the left side, there is a rocky hillside. In the distance, a red barn is visible. The background shows a dense forest of evergreen trees under a cloudy sky.

Date/Name	Photo
<p>Photo 13: 10/1/2014 Gold Run, just south of 84 Gold Run Road, looking north.</p>	
<p>Photo 14: 10/1/2014 Gold Run Road, looking west from 84 Gold Run Road.</p>	

Date/Name	Photo
<p>Photo 15: 10/1/2014 Culvert on south side of Gold Run Road.</p>	
<p>Photo 16: 10/1/2014 Gold Run on south side of Gold Run Road, looking west.</p>	

Date/Name	Photo
<p>Photo 17: 10/1/2014 Gold Run Road, looking west.</p>	
<p>Photo 18: 10/1/2014 Gold Run and Gold Run Road, looking east towards 84 Gold Run Road.</p>	

Date/Name	Photo
<p>Photo 19: 10/1/2014 84 Gold Run Road, looking northeast.</p>	 A photograph of a white, two-story house with a gabled roof and a stone retaining wall in the foreground. The house is situated on a hillside with trees and a dirt road in the foreground.
<p>Photo 20: 10/1/2014 Gold Run Road and rock face at parking area for 84 Gold Run Road, looking east.</p>	 A photograph of a dirt road with several vehicles parked on the left side. A large rock face is visible on the right side of the road, and trees are in the background.

Date/Name	Photo
<p>Photo 21: 10/1/2014 Fourmile Canyon Drive just east of intersection, looking east.</p>	
<p>Photo 22: 10/1/2014 Fourmile Creek south of Fourmile Canyon Drive, looking east.</p>	

Date/Name	Photo
<p>Photo 23: 10/1/2014 Fourmile Canyon Drive east of intersection, looking east.</p>	
<p>Photo 24: 10/1/2014 Aspen trees on north side of Fourmile Canyon Drive east of intersection.</p>	

Date/Name	Photo
<p>Photo 25: 2/27//2014 Inactive nest in Douglas fir tree east of intersection on the south side of Fourmile Canyon Drive.</p>	 A close-up photograph of a Douglas fir tree branch. The branch is dark brown and has several green, needle-covered sub-branches extending from it. A small, cup-shaped nest is visible in the fork of the branch, partially obscured by the needles. The background is slightly blurred, showing more of the tree and some sky.
<p>Photo 26: 2/27/2014 Inactive nest in Douglas fir tree east of intersection on the south side of Fourmile Canyon Drive.</p>	 A wide-angle photograph of a Douglas fir tree in a snowy landscape. The tree is the central focus, with its dark trunk and green needles contrasting against the white snow on the ground. Other trees are visible in the background, and the overall scene is a winter forest setting.